


20711 RIO ORO DR

00129764

5/21/08

marliwr

Groundwater and Wastewater Services File Imaging Project
May 2007
*Barcode Font = IDAutomationHC39M*

00129 T 04
1972 3564

# Mecklenburg County
## Health Department

December 12, 1991

Corporate Homes Division
Attn: Carol Grantham
6618 Fairview Road
Charlotte, N.C. 28210

Dear Ms. Grantham:

At your request, an investigation was made of the septic tank system and a well water sample was collected on the property located at 20711 Rio Oro Drive Charlotte, North Carolina, on November 20, 1991.

At the time of the investigation there was no effluent apparent on the surface of the ground.

The results of the water sample are inconclusive as this residence is connected to a community water system.

Please contact the Department of Environmental Protection at 336-5500 for further information regarding the community Well.

If you have any questions concerning this matter, please contact me at 376-4603 between 4:00-5:00 p.m.

Sincerely,

Sylvia D. Daniel for Tim Whittaker

Timothy Whittaker, R.S.
Individual Water and Wastewater Systems

CC: Rusty Rochelle Britt Setzer, DEM
~~ENVIRONMENTAL~~ WATER QUALITY PROGRAM, DEA Mooresville

BEGIN USING THIS FORM WHEN YOU GET A POSITIVE ON A COMMUNITY WELL — A SERVICE REQUEST MUST BE SENT TO WATER QUALITY 12-12-91

Environmental Health Division
1200 Blythe Boulevard • Charlotte, North Carolina 28203 • (704) 376-4603