Date Received 7-16-73

APT No 6671

T. C. No _____

Map Date _____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Mc Lee (LAST) Samuel (FIRST) H (MIDDLE)

2) ADDRESS OF OWNER 1 Hillcrest Dr. Charlotte, N.C. ZIP 28213

3) PHONE NO Home 523-2926 Office _____


4) LOCATION OF PROPERTY S/S 3113 (STREET OR COUNTY ROAD) _____

5) SUBDIVISION _____ LOT NO 1 BLOCK NO. _____

MAP BOOK NO. 137 PAGE NO. 13

6) DEED REFERENCE DEED BOOK 3593 PAGE NO 203

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Samuel H. McLee
OWNER

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203
Telephone 374-2113

Date Issued
1. July 20, 1973
2. _____
3. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

SDR No. 6671
T.C. No. P.O. 137-121-18
9-29-71

NAME OF OWNER Yeven, Samuel A.

ADDRESS OF OWNER Route 1, Box 430-C ZIP 28212

LOCATION OF LOT County Road 3115, Lot 1

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
A X	1.	7-10-73	160 min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

J. M. Reynolds
Environmentalist

(Stencil No.)
EHD 398
8/70

FORM NO.
E-19-8-14-70

MECKLENBURG COUNTY HEALTH DEPARTMENT
INTER-OFFICE COMMUNICATION

DATE: July 24, 1973

TO: Randy Reynolds, Environmentalist

FROM: W. Everette Lynn, Jr. W. E. L.
Soil Scientist

SUBJECT: Soil investigation on Lot No. 1, C. R. 3115, APT - 6671

A soil investigation was made on Lot No. 1, on C.R. 3115, on July 23, 1973, to determine site suitability for a septic tank system. The soils were found to be of the Helena series and alluvial soils with a seasonal high water table. The Helena soils occur on the front of the lot (adjacent to C.R. 3115). These soils have plastic clay subsoils which contain swelling clay minerals. This results in slow perc and a perched high water table. The alluvial soils on the rear of the lot also have a high water table.

Based on these investigations, it is recommended that the lot be disapproved for installation of a septic tank system.