S. I. R. NO. 6569

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

T. C. # 013-014-43, 42, 41, 44

(Ground Absorption Sewage Disposal)

OWNER: LAYLOR HARRIS JR
ADDRESS: 2300 LATE ST.
COUNTY: DURHAM 27716
LOCATION OF SITE: PAMELA ST. LOT 3, 4, 5, 6

DATE REQUESTED:
PLAT NO.:
LOT SIZE: 23,755

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-10 U	S PS 0-5 (U)	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy loamy clayey, Note 2 1 Clay)	S PS 2-1 (U)	S PS 2-1 (U)	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S PS (U) MASSIVE	S PS (U) MASSIVE	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS (U) 24	S PS (U) 48	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S PS (U)	S PS (U)	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & internal)	S PS (U)	S PS SLOW (U)	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS (U)	S PS SLOW (U)	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	UNSUITABLE	UNSUITABLE		
SOIL SERIES	CREEDMOOR	ENON		

S - Suitable PS - Provisionally Suitable U Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies wet areas, fill areas, wells, water bodies, slope patterns, etc

Recommendations/Comments

Described By: D. B. [illegible]

Title: soil scientist Date: 1-14-80

3

DHS Form 2691
Sanitation
EHD 539 (3/79)

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 6569

T.C. # 013-014-43,42,41&40

DATE January 16, 1980

NAME OF OWNER Mr. Taylor Harris, Jr.

ADDRESS OF OWNER 2300 Tate Street, Charlotte, NC 28216

LOCATION OF LOT Pamela Street Lots 3,4,5 and 6

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist