Date Received 1/6/80

APT No. 16421

T. C. No. 109-341-07

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Hatfield (LAST) Mary (FIRST) Mrs. Mary's F. (MIDDLE)

2) ADDRESS OF OWNER 15425 Sherman Way CALIF. ZIP 91406

3) PHONE NO Home 213 782 3580 Office _____


4) LOCATION OF PROPERTY lot #7 on Brickstone Drive (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO 07 BLOCK NO. 341

MAP BOOK NO 109 PAGE NO _____

6) DEED REFERENCE DEED BOOK 1699 PAGE NO 307

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of soil investigations and the inspection of the property hereinabove described for the purpose of determining if the soil is suitable for the installation of an on-site subsurface sewage disposal system with subsurface soil absorption effluent disposal.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Mary F. Hatfield
OWNER

EHD-5-76

Environmental Health Department's Copy

Date Received 1/9/80

MECK. COUNTY DEPARTMENT OF ENVIRONMENTAL HEALTH
JAN 9 1980

APT No. 16421
T C. No. 109-341-7
Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Finster (LAST) Earl (FIRST) John (MIDDLE)

2) ADDRESS OF OWNER 3125 Sinclair Cir. Charlotte ZIP 28205

3) PHONE NO Home 537-4139 Office 562-9920


4) LOCATION OF PROPERTY Brickstone Drive - Pineburr Rd
STREET OR COUNTY ROAD

5) SUBDIVISION LOT NO 7 BLOCK NO

MAP BOOK NO 109 PAGE NO 341

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Earl John Finster
OWNER

EHD-5-76

Environmental Health Department's Copy

S. I. R. NO. 16421

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

T. C. # 102-341x77

(Ground Absorption Sewage Disposal)

OWNER: Mary F. Whitfield
ADDRESS: 1525 Vermont Way
COUNTY: San Diego, California
LOCATION OF SITE: Rancho Vista

DATE REQUESTED:
PLAT NO.: Lot #28
LOT SIZE: 17,150 sq. Ft.

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U 2-8%	S PS (U) complex slopes exceed	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy clayey, Note 2 1 Clay)	S (PS) clay U	S (PS) clay U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S (PS) Blocky U	S (PS) Blocky U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS U 40"	S Depth PS Variable (U)	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata Rock)	(S) None PS U	(S) None PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & internal)	(S) PS U 76" to groundwater	S Eroded PS Areas (U) channel water	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) Moderate U	S (PS) Moderate U	S PS U	S PS U
8. OTHER (Specify)	S Inadequate PS Area (U) < 20,000 sq. Ft.	S PS	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable	unsuitable		
SOIL SERIES	Cerri	complex slopes Exidal		

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies wet areas, fill areas, wells, water bodies, slope patterns, etc


Recommendations/Comments

Described By: William R. Martin

Title: Soil Scientist Date: 1-22-80

DHS Form 2601
Sanitation
EHD 539 (3/79)

2


50'
complex slopes
cecil
342.8'
complex slopes
cecil
50'
Brickstone

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 16421

T.C. # 109-341-07

DATE January 22, 1980

NAME OF OWNER Hatfield, Mary

ADDRESS OF OWNER 15425 Sherman Way, Van Nuys, Calif. 91406

LOCATION OF LOT Brickstone Drive (parcel #07), Lot 98

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Limited area of provisionally suitable soils.

Please submit plot indicating location of proposed residence and sewage disposal system.

John R. Adkisson

John R. Adkisson, Environmentalist

SEE INSTRUCTIONS ON BACK

Date Received 1/29/80

ICAR(S) Application No [illegible]

T C No [illegible]


Map Date [illegible]

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

Application for an
Installation, Construction, Alteration, and/or Repair Permit
Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge

The owner of that property described hereinafter hereby applies to the Mecklenburg County Department of Environmental Health for a permit to

1 Install 2 Construct 3 Alter 4 Repair an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



3 PLOT PLAN (ACCURATELY DIMENSIONED)

Mobile Home ___Yes X No
Residence X Yes ___ No
4. No of Bedrooms 3
5. Business Use – Max No Employees ___
6. Washing Machine X Yes ___ No
7. Garbage Disposal X Yes ___ No
8. Dishwasher X Yes ___ No
9. Water Supply
A. Individual Well X
B. Governmental System ___
C. Community System
1. Well source ___
2. Governmental source ___
10. Sewage System
House located within 200 feet of public sewer ___ Yes X No
House located within 200 feet of community sewer ___ Yes ___ No
11. EHA Case No ___
12. VA Case No ___

13) NAME OF OWNER [illegible] (LAST) [illegible] (FIRST) [illegible] (MIDDLE)

14) ADDRESS OF OWNER [illegible]

15) PHONE NO Home [illegible] Office [illegible]

16) LOCATION OF SYSTEM [illegible] (STREET OR COUNTY ROAD)

17 SUBDIVISION [illegible] Lot No [illegible] Block No [illegible]

Map Book No [illegible] Page No [illegible]

18) DEED REFERENCE — DEED BOOK [illegible] AT PAGE [illegible]

19. HAS A SOIL INVESTIGATION BEEN RUN? X YES NO DATE RUN [illegible]

20) PTR NUMBER (See Instructions) [illegible]


The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

DATE OF APPLICATION [illegible]

OWNER [illegible]

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY


50
83.6
59.5'
160'
49'
25'
10'
Septic Tank
Septic Line
Slopes
40'
16
23.5'
7'
44
44
89'
19.5
23.5'
2'
94'
30'
Well
44'
50
DRICKSTONE

Date Issued January 28, 1980 Serial No. 3877

LA No. 16421

T C No 109-341-07

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Hatfield, (LAST) Mary (FIRST) F. (EARL FINSTER, BUILDER) (MIDDLE)

ADDRESS OF OWNER 15425 Sherman Way, California ZIP

LOCATION OF LOT Brickstone Drive (STREET OR COUNTY ROAD)

SUBDIVISION LOT NO #7 BLOCK NO.

MAP BOOK NO PAGE NO

The above specified lot is approved by the Mecklenburg County Department of Environmental Health for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge based on the soil investigation, on an on-site inspection of the said lot; and upon the information supplied in the "Application for an Installation, Construction, Alteration, and/or Repair Permit", number 16421. This approval is subject to the following terms and conditions:

1. That the nitrification field be installed, constructed, altered and/or repaired in the same area where the soil investigation was run
2. That an "Installation, Construction, Alteration and/or Repair Permit" be issued and in full force and effect when the system is installed constructed, altred, and, or repaired and that the system be installed in accordance with same

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic-tank system is not being installed, constructed, altered and/or repaired in accordance with a valid Installation, Construction, Alteration, and/or Repair Permit

Environmentalist

John R Atkisson

Environmental Health Director, or Authorized Section Head

EHD-5-76

Environmental Health Department's Copy