Date Received 3-22-83

MECK COUNTY DEPARTMENT OF
RECEIVED
MAR 22 10
ENVIRONMENTAL HEALTH

SIR No. 19423

T. C. No. PO 015-263

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Woodside (LAST) Dale (FIRST) Thomas (MIDDLE)

2) ADDRESS OF OWNER Rt 3, Box 955 Huntersville n.c. ZIP 28078

3) PHONE NO. Home 394-3630 Office


4) LOCATION OF PROPERTY Shields (STREET OR COUNTY ROAD) Dr.

5) SUBDIVISION LOT NO. 15 BLOCK NO.

MAP BOOK NO. PAGE NO

6) DEED REFERENCE: DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

J. T. Woodside
OWNER

EHD-5-76

Environmental Health Department's Copy

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 1973

T.C. NO. PO 015-76309

(Ground Absorption Sewage Disposal)

OWNER: Jesse T. Woodside
ADDRESS: Rt 3 Box 455 Huntersville N.C.
LOCATION OF SITE: Linville

PLAT NO: Lot #15
LOT SIZE: 22,430

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U	S Complex PS slopes (U)	(S) PS 2-8% U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S (PS) clay U	S (PS) Clay U	S PS ____ U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) Blocky U	S (PS) Blocky U	S PS ____ U	S PS U
4. SOIL DEPTH (inches)	S 36-40" (PS) U	S Depth Variable (U)	S PS U ____	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S Saprolite 36"+ (PS) U	S Saprolite PS 36" or less (U)	S PS ____ U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	(S) ground water 48"+ PS U	S Eroded PS Areas channel water (U)	S Drainage PS Way (U)	S PS U
7. OTHER (Specify)	S Restrictive PS Area (U)	S PS U	S PS U	S PS U
8. SOIL GROUP	IIA	IIA	IIA	
9. SITE CLASSIFICATION	unsuitable	unsuitable	unsuitable	
10. SOIL SERIES	Cecil Lina	Evedal complex slopes	Driveway	

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments: _____

Described by: William A. Martin
Title: Soil Scientist

Date: 3-29-83

EHD 539 (Revised: 6/82)

2/


130'
complex slopes
Driveway
Approx
110'
211'
211'
Approx 60'
Center line
shields
130'

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 19473
T. C. NO. PO 015-263-08
DATE: 3-30-83

Mr. Galer T. Woodside
Route 3, Box 955
Huntersville, NC 28078

Re: Property located at Shields Drive, Lot 15

Dear Mr. Woodside:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, please submit your proposals, in the form of plans and specifications, to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of a "Septic Tank Agreement Form" provided by this office.

If I may be of assistance, please feel free to call at any time.

Sincerely,

Mike Sexton

Michael A. Sexton
Environmentalist
On Premises Waste Disposal Section

Enclosure

EHD #37 (11-82)