Date Received 3/21/78

APT No. 13760

T. C. No. 25-132

Map Date 3-9-71

Robert E. Dreyer 366-7036
4226 Wright ave. Charlotte, N.C. 28211

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Duskin Isaac (LAST, FIRST, MIDDLE) Americana Park Inc

2) ADDRESS OF OWNER _____ ZIP _____

3) PHONE NO. Home 366-5762 Office Shamrock realty Co.


4) LOCATION OF PROPERTY AMERICANA PK [redacted] MIAMI CK. (STREET OR COUNTY ROAD)

5) SUBDIVISION AMERICANA LOT NO 18 & 21 BLOCK NO. _____

MAP BOOK NO 112 PAGE NO 13

6) DEED REFERENCE DEED BOOK 22 PAGE NO 363

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge




7) ACCURATELY DIAGRAM & DIMENSION LOT

Americana Park Inc.
Duskin Isaac
OWNER

EHD-5-76

Environmental Health Department's Copy


#2110
Unsuitable soils for septic tank installation
MARGINAL SOILS FOR SEPTIC TANK INSTALLATION
Suitable Soils for septic tank installation
14.2 AC.
16.52 AC.
135
133
132
ARIZONA CIR
SAN FRANCISCO CIR
EL MUNDO ST.
BLVD.
BLOCK
LINE
TAX LINE MAP
MECKLENBURG COU
REVISED
PG. 18

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

13760
SIR.NO. ~~026-132-18, 19,~~ 20 & 21
T.C. NO. ~~2-8-1976~~
MAP DATE
DATE ~~5-30-78~~

NAME OF OWNER Luski Isaac

ADDRESS OF OWNER Shamrock Realty Company, 4935 Albermarle Road

LOCATION OF LOT Miami Circle, Lots 18, 19, 20 & 21

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil structure massive

Inadequate area available for installation of ground absorption sewage disposal system in accordance with North Carolina Department of Human Resources specifications.

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA:jjk

EHD 398
7/77

R

Date Received Oct. 12, 1978

APT No. 13760

T. C. No. [illegible]

Map Date [illegible]

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER [illegible] (LAST FIRST MIDDLE)

2) ADDRESS OF OWNER [illegible] ZIP [illegible]

3) PHONE NO Home [illegible] Office [illegible]


4) LOCATION OF PROPERTY MIAMI CIRCLE (STREET OR COUNTY ROAD)

5) SUBDIVISION [illegible] LOT NO [illegible] BLOCK NO [illegible]

MAP BOOK NO [illegible] PAGE NO [illegible]

6) DEED REFERENCE DEED BOOK [illegible] PAGE NO [illegible]

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on-site inspection of the property hereinafter described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

[illegible]
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

(Ground Absorption Sewage Disposal)

APT 13760
TC 025-132-M32931

OWNER: John Ramadan
ADDRESS: 10 Wampum Trail Way
COUNTY: Charlotte, N.C.
LOCATION OF SITE: Mint Hill

DATE REQUESTED:
PLAT NO.:
LOT SIZE: 2 Acre

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS 2-8% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S PS 2-1 (U) Clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S Massive PS (U)	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) 48" PS U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Imprevious Strata, Rock)	(S) None PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) 76" to PS ground U water	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S Slow PS Very (U) slow	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable			
SOIL SERIES	Enon			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)

Recommendations/Comments:

Described By: William R Mullen

Title: Asst Supervisor Date: 10-23-79

DHS Form 2601 (2/77)
Sanitation


84'
145'
90'
E Wall
80'
40' Main
Potomac
112'
295'

MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR. NO. 13760
T. C. No. 025-132-18,19,20,21
MAP DATE Aug. 7, 78
DATE October 25, 1978

NAME OF OWNER Ramadan, John

ADDRESS OF OWNER 18 Wynbrook Way

LOCATION OF LOT Miami Circle , lots 18,19,20,21

At your request and pursuant to Section .1900 of the North Carolina Administrative Code, Title 10, Department of Human Resources, Chapter 10, Health Services, Subchapter 10A, a site evaluation has been made for an on premises ground absorption sewage disposal system on the property designated above and the following conditions were found:

Soil Structure Massive
Soil Permeability Unsuitable

Section 10 fo the North Carolina Administrative Code 10A, .1910 of these regulations states "Sites originally classified as unsuitable may be used for soil absorption disposal systems, provided engineering, hydrogeologic, and soils studies indicate to the local agency that a suitable alternate system can reasonably be expected to function satisfactorily.

Section 10, North Carolina Administrative Code 10A, .1916 states that "The design, construction, and maintenance of ground absorption sewage systems, whether septic tank systems or alternate systems shall be the responsibility of the owner, developer, installer, and user of the system as applicable in the circumstances".

We would also advise you that according to Regulation 10, North Carolina Administrative Code 10A, .1916(b), "Actions of representatives of state or local agencies engaged in the evaluation and determination of measures required to effect compliance with the provisions of this section shall in no way be taken as a guarantee that sewage disposal systems approved and permitted will function in a satisfactory manner for any given period of time or that such employees assume any liability for damages, consequential or direct, which are caused or which may be caused, by a malfunction of such system.

These regulations became effective July 1, 1977. Since that time the second sentence of Section .1910(c) has been found to be nugatory. For this reason, if you desire to file for permission to install an "alternate" system you should present this office with your proposals in the form of plans and specifications. These would be reviewed and if it is found that the system may reasonably be expected to function satisfactorily approval may be given on the execution by you of a "Septic Tank Agreement Form" available in this office.

EHD #584

R