W

Date Received 9-24-73

APT No. 7032

T C No. 211-201-10

Map Date 4-22-73

msg Rs to:
Southern Bell
375 S. Tryon St.
P.O. Box 240
Room 521
Charlotte, N.C. 28201
Attn: Mike Tooley
333-7711 Ext 8

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER J. M. HARRY & BRYANT CO., INC.
(LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER 500 PROVIDENCE ROAD, CHARLOTTE, N. CAR. ZIP 28207

3) PHONE NO Home _____ Office 332-7133


4) LOCATION OF PROPERTY CARMEL ROAD, MECKLENBURG COUNTY, N. CAR.
(STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO _____ BLOCK NO. _____

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK 211 PAGE NO 201

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

J. M. HARRY & BRYANT CO., INC.

BY: _____ SEC.-TREAS.
OWNER

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203
Telephone 374-2113

Date Issued
1. September 26, 1973 SITE DISAPPROVAL REPORT SDR No. 7032
2. _____ INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, T.C. No. _____
3. _____ SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER J. N. Harry & Bryant Co., Inc.

ADDRESS OF OWNER 500 Providence Road ZIP 28207

LOCATION OF LOT Carmel Road

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	9-25-73	200 min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

X ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) 9-25-73 - relocate test holes in general area of proposed disposal field.

Thomas B. Wade
Environmentalist

(Stencil No.)
EHD 398
8/70

FORM NO.
E-19-8-14-70

Serial No. 3858

PTR No 7032

Date Issued December 5, 1973

T C No 211-201-10

Map Date 4-27-73

Do Not Issue A Building Permit Based On This Form

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION


PERCOLATION TEST REPORT

NAME OF OWNER J. M. Harry & Bryant Co., Inc.
(LAST FIRST MIDDLE)

ADDRESS OF OWNER 500 Providence Road ZIP 28207

LOCATION OF PROPERTY Carmel Road
(STREET OR COUNTY ROAD)

SUBDIVISION LOT NO BLOCK NO



PLOT PLAN

This is to certify that a percolation test has been run and an on-site inspection made by the Mecklenburg County Health Department on the lot described above. The said test was conducted on that portion of the lot as indicated on above plot.

The percolation rate determined by the test was 60 min/in. The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge subject to the following terms and conditions:

1. A permit to install, construct, alter, or repair the specific system shall be obtained from the Mecklenburg County Health Department prior to the beginning of any construction of buildings, or of the wastewater treatment system on the said lot.
2. The size of the septic tank wastewater treatment system which must be installed will be determined by the Health Department prior to installation based on the percolation rate obtained above, and on the size and type of building constructed thereon.
3. This approval is valid only if the system is installed in the immediate area where the percolation test was run.
4. This approval is void if any grading, filling, or construction (including the drilling of a well) is performed on the lot which, in the opinion of the Health Department, renders the area where the percolation test was run unsuitable for the installation, construction, alteration and/or repair of such a system.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina State Board of Health and the Mecklenburg County Board of Health which were in effect on the date of issuance and is void if at any time in the future, prior to the completion of the system, these laws, rules, and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

John R. Henderson

Director, Environmental Health Division or
Authorized Section Head

FORM NO E-2-9-1-72

HEALTH DEPARTMENT'S COPY

A

SEE INSTRUCTIONS ON BACK

Date Received 5-13-74

ICAR(S) Application No 7032

T C No 211-201-10

Map Date 4-27-73


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge

The owner of the property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to

1) Install or Construct 2) Alter or Repair an individual septic tank wastewater treatment system with a subsurface soil absorption, effluent discharge



3) PLOT PLAN (ACCURATELY DIMENSIONED)

4) No of Beds C

5) Estimated Water Use Employee 2

6) Washing Machine ... ✓ No

7) Garbage Disposal ... ✓ No

8) Dishwasher ... ✓ No

9) Any other wastes ...

A ...

B ... ✓

C ...

D ...

E ...

F ... ✓ No

G ... ✓ No

H ... No

I ...

J ...

13) NAME OF OWNER Southern Bell Telephone and Telegraph Company
LAST FIRST MIDDLE

14) ADDRESS OF OWNER P.O. Box 240

15) PHONE NO Home ... Office 373-8698

16) LOCATION OF SYSTEM CARMEL ROAD
STREET OR COUNTY ROAD

17) SUBDIVISION ... Lot No ... Block No ...

Map Book No ... Page No. ...

18) DEED REFERENCE — DEED BOOK 211 AT PAGE 20 AR>60

19) HAS A PERCOLATION TEST BEEN RUN? ✓ YES ... NO DATE RUN 12-5-73

20) PTR NUMBER (See Instructions) 7032

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

MAY 13, 1974
DATE OF APPLICATION

OWNER Building Engineer

FORM NO E-4-9-1-72

HEALTH DEPARTMENT'S COPY

Date Issued May 13, 1974

Serial No. 4059

LA No 7032

T C No 211-201-10

Map Date 4-27-73

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Southern Bell Telephone and Telegraphy Company
(LAST / FIRST / MIDDLE)

ADDRESS OF OWNER P.O. Box 240 ZIP _____

LOCATION OF LOT Carmel Road
(STREET OR COUNTY ROAD)

SUBDIVISION _____ LOT NO _____ BLOCK NO _____

MAP BOOK NO _____ PAGE NO _____

The above specified lot is approved by the Mecklenburg County Health Department for the installation of an individual septic tank system with subsurface, soil absorption effluent discharge based on the percolation test results which yielded a percolation rate of 60 min/in on an on-site inspection of the said lot, and upon the information supplied in the "Application for an Installation Construction, Alteration, and/or Repair Permit" number 7032. This approval is subject to the following terms and conditions

1. That the nitrification field be installed, constructed, altered, and/or repaired in the same area where the percolation test was run.
2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altred, and/or repaired and that the system be installed in accordance with same.

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic-tank system is not being installed, constructed, altered and/or repaired in accordance with a valid installation, Construction, Alteration, and/or Repair Permit

Environmentalist

John R. Adkisson
Director, Environmental Health Division or Authorized Section Head

FORM NO E-3-9-1-72

HEALTH DEPARTMENT'S COPY

Date Issued 25 July 74 Serial No. 3 ICAR(S) Permit No 7032

T C No 211-201-16

Map Date 22 Apr 73


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

INSTALLATION, CONSTUCTION, ALTERATION, AND/OR REPAIR PERMIT

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Permission is hereby given to ✓ Install or Construct Alter or Repair the individual septic tank waste water treatment system with subsurface, soil absorption effluent discharge as specified herein at the described location. This permit is granted based upon the information supplied in application 7032, dated 13 May 74. If this permit shall be void and of no effect if the information provided in the application is not true and complete. All work shall be completed on or before 25 Aug 74 after which date this permit shall be null and void



PLOT OF SYSTEM

Percolation Rate 60

Liquid Capacity of Tank 1000

Tank Construction PC

Absorption and/or Nitrification Lines

Total Length 300'

Number of Lines 6 (21 x 50' @ 19")

Distance from House 10'

Distance from Property Line 10'

Distance from Well City

NAME OF OWNER Southern Bell Telephone & Telegraph Co.

LOCATION OF PROPERTY Carmel Rd.

The system shall meet all of the construction requirements as set forth in the Regulations of the Mecklenburg County Board of Health which are in effect on the date of the granting of this permit. A certificate of approval must be issued by the Health Director before any system can be covered up or otherwise rendered uninspectable or can be used

Comments Chamber Manure (Cont.)

Division of Septic Tank Control

M. L. Kirby
Environmentalist

If this permit is for the installation or construction of a new system, it must be signed by the division or a district health department Environmental Health Division in order to be valid. Only the signature of the Environmentalist is required where an existing system is being altered or repaired

Form E-5-9-1-72

White Copy - Permit Card

C of A (s) No 7032

Serial No. [illegible]

Date Issued 25 July 74

T C No 211-2014

Map Date 27 Apr 73

CERTIFICATE OF COMPLETION

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

CERTIFICATE OF APPROVAL

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Name of Owner Southern Bell Telephone & Telegraph Co.
LAST FIRST MIDDLE

Location of Property Carmel Rd.

Application Number 7032 Permit Number 7032

Inspection Data:

Liquid Capacity of Tank 1000 Tank Material PC

Total Length of Drain Tile 300' Number of Lines 6 (25'X50'X17")

Depth of Filter Material 17" Cover Depth 18"-24"

Water Supply Source City Distance from Water Source *

Excavation Inspected 25 July 74 DATE Tank Inspected 25 July 74 DATE

Nitrification Field Inspected 25 July 74 DATE

Washing Machine Line Inspected If Applicable ____ DATE

The undersigned has inspected the Individual Septic Tank System with subsurface, soil absorption effluent disposal as described above and it has been ✓ installed or constructed. It is hereby approved in accordance with the permit issued and the regulations of the Mecklenburg County Board of Health effective on the date of issuance of the permit. The issuance of this Certificate of Approval does not in any way guarantee that the system will operate properly or relieve any person, firm or corporation owning or using such system from any liability resulting from the failure of the system to operate properly. This Certificate of Approval is issued subject to those restrictions and conditions shown on the permit and in addition to those listed below under comments. This Certificate of Approval shall be null and void if any information contained in the application is untrue or if any additions are made to the property which would increase the requirements for said system.

Comments Caution Manhole (Center)

Environmentalist

FORM NO E-6-9-1-72

HEALTH DEPARTMENT'S COPY