Date Received 4-26-73

APT No. 6107

T. C. No. 211-192-17

Map Date 4-7-72

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Ross (LAST) Company (FIRST), Ltd. (MIDDLE)

2) ADDRESS OF OWNER 3841 Bonnard Drive ZIP

3) PHONE NO Home 364-5110 Office


4) LOCATION OF PROPERTY Lynn Ave. (STREET OR COUNTY ROAD)

5) SUBDIVISION Carmel Hills LOT NO. 17 BLOCK NO.

MAP BOOK NO 211 PAGE NO. 173

6) DEED REFERENCE: DEED BOOK 2895 PAGE NO. 218

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and on on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

By: Martha Whitley
OWNER Real Estate Agent for
Lee Kinney Realty and
Bobbie Ross, owner of
Company

FORM NO. E-1-S-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT

INTER-OFFICE COMMUNICATION

DATE: August 10, 1973

TO: Tom Ward
Environmentalist

FROM: W. Everette Lynn, Jr. W. E. L.
Soil Scientist

SUBJECT: Lynn Avenue, Lot 17
APT #6107 (Ross Co., Ltd.)

8-8-73 Soils are of the Wilkes and Iredell soil series. These soils have very plastic and sticky clay subsoils which contain swelling clay minerals. The Iredell soils also have a perched high water table during periods of high rainfall. The Wilkes soils are shallow to impervious rock material. These factors result in inadequately slow perc. and permeability. Based on these observations, disapproval is recommended.

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. June 7, 1973
2. _____
3. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

SDR No. 6107
T.C. No. P.O. 211-192-17 4-7-72

NAME OF OWNER Foss Company, Ltd.

ADDRESS OF OWNER 3841 Rowwood Drive ZIP _____

LOCATION OF LOT Lynn Avenue, Lot 17

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	6-6-73	250 min/in
X	2.	8-7-73	120' min/in
X	3.	10-24-73	160 min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

Thomas R. Ward
Environmentalist

(Stencil No.)
EHD 398
8/71

FORM NO.
E-19-8-14-70