Date Received 2/7/79

APT No. 15095

T. C. No. P.O. 15-092-08

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Vogel (LAST) Paul (FIRST) A. (MIDDLE)

2) ADDRESS OF OWNER 223 Waverly Dr Monroe NC ZIP 28110

3) PHONE NO Home 283-2256 Office 521-9477


4) LOCATION OF PROPERTY Independence Blvd (STREET OR COUNTY ROAD) at County Line

5) SUBDIVISION _____ LOT NO 5 BLOCK NO. _____

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and on on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Paul A. Vogel

OWNER

EHD-5-78

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

S.I.R. No. 15095

(Ground Absorption Sewage Disposal)

OWNER: Paul A. Wolfe
ADDRESS: 2239 Winecoff Ln.
COUNTY: Cabarrus, N.C. 28116
LOCATION OF SITE: Highway 73 E

DATE REQUESTED:
PLAT NO.: PC 215-C92-CE Lot 5
LOT SIZE: 15,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	~~S~~ PS 2-6% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S L-1 PS ~~U~~ Clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils) ✔	S Massive PS ~~U~~	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	~~S~~ 48" PS U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S None PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal) ✔	S Seasonal PS Perched U ~~water Table~~	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate) ✔	S PS 0 Slow U	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION ✔	Acceptable			
SOIL SERIES	Helena			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns)


Recommendations/Comments:

Described By: William G. Franklin

Title: Soil Scientist Date: 2-20-79

dhs form 2601 (1/79)
Sanitation

3


Additional Area Needed
3-13-94 Mtg.
150'
500'
500'
150'
Highway 74

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

SIR.NO. 15085
T.C. NO. po 215-092-08
MAP DATE
DATE February 21, 1979

NAME OF OWNER Paul A. Vogler

ADDRESS OF OWNER 2238 Waverly Drive

LOCATION OF LOT Highway 74, East (Independence Blvd.) Lot #5

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Structure Massive

Perched Water Table

Soil Permeability Unsuitable

Site Classification Unsuitable

Stephen J. Wood, Environmentalist

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR. NO. 15005
T.C. NO. pe-215-002-08
MAP DATE
DATE March 15, 1979

NAME OF OWNER Paul A. Vogler

ADDRESS OF OWNER 2238 Waverly Drive

LOCATION OF LOT Independence Blvd., Lot 5

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Structure Massive

Soil Drainage: Seasonal Perched Water Table

Soil Permeability Unsuitable

Site Classification Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist