Date Received 2/31/29

APT No. 16007

T. C. No. 001-134-17

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER JBS Corporation (LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER RFD. 1, Box 60, Davidson, N. C. ZIP 28036

3) PHONE NO. Home _____ Office _____


4) LOCATION OF PROPERTY Lot 17A, Norman Colony Rd. (STREET OR COUNTY ROAD)

5) SUBDIVISION Norman Colony LOT NO. 17A BLOCK NO. _____

MAP BOOK NO 15 PAGE NO. 45

6) DEED REFERENCE: DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

JBS Corporation
By: J B Sales
OWNER

EHD-S-75

Environmental Health Department's Copy

S. I. R. NO. 6007

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

T. C. # 001-134-17

(Ground Absorption Sewage Disposal)

OWNER: J B S Corporation
ADDRESS: R.L. Davie, Davidson 27036
COUNTY:
LOCATION OF SITE: Denton Tolary

DATE REQUESTED:
PLAT NO.: L 17A
LOT SIZE: 2 +/- Acre

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS 2-8% U	S complex PS (U)	(S) 2-8% PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 Clay)	S (PS) Clay U	S (PS) Clay U	S PS 2-1 (U) Clay	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S (PS) Blocky U	S (PS) Blocky U	S PS massive (U)	S PS U
4. SOIL DEPTH (In.)	(S) 48" PS U	S Depth Variable PS (U)	(S) 48" PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata Rock)	(S) None PS U	(S) None PS U	(S) None PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & internal)	(S) 36-70 ground water PS U	S Eroded Areas Channel water PS (U)	S Seasonal high water Table Drainageway PS (U)	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) Moderate U	S (PS) Moderate U	S Slow PS (U) V. Slow	S PS U
8. OTHER (Specify)	S Inadequate Area of PS Arrable (U) Soils	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable	unsuitable	unsuitable	
SOIL SERIES	Cecil	Complex Slopes	Helena-Drainageway?	

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies wet areas, fill areas, wells, water bodies, slope patterns, etc.


Recommendations/Comments: _____

Described By: _____

Title: _____ Date: _____

DHS Form 2601
Sanitation
EHD 539 (3/79)

2


complex slums
2.79'
Helena
Drainage way
65'
156'
ccc.d
2-8-0
21
Norman Colony Rd
130'

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. No. 16007
T.C. No. 001-134-17
MAP DATE
DATE 8/14/79

NAME OF OWNER JBS Corporation

ADDRESS OF OWNER Route 1, Box 60, Davidson, NC 28036

LOCATION OF LOT Norman Colony Road, Norman Colony subdivision LOT 17A BLK.

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system due to the following reasons:

Inadequate area available for installation of ground absorption sewage disposal system in accordance with North Carolina Department of Human Resources specifications.

Please submit plot of proposed dwelling and system location.

John R. Adkisson

John R. Adkisson, Environmentalist