Date Received 7/23/79

MECK COUNTY DEPARTMENT OF
RECEIVED
JUL 30 1979
ENVIRONMENTAL HEALTH

APT No. 15962
T. C. No. 80 143-131-12
Map Date 1/3/79

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

(95 acres)

#1
2nd DUPLEX

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER THE LAMB'S CHANCE - HARRY BIZZELL
(LAST, FIRST, MIDDLE)

2) ADDRESS OF OWNER RT 2 BOX 428 CLT. N. C. ZIP 28216

3) PHONE NO. Home 523 6581 Office SAME


4) LOCATION OF PROPERTY OFF BERDEN RD (LAKE RD)
(STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO. _____ BLOCK NO. _____

MAP BOOK NO. 143 PAGE NO. 12

6) DEED REFERENCE: DEED BOOK 3495 PAGE NO. 563

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER Harry Bizzell Jr.

FORM NO. E-1-11-1-70

HEALTH DEPARTMENT'S COPY

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

APT 15962

(Ground Absorption Sewage Disposal)

OWNER: The Lamb's Chapel Home Builders DATE REQUESTED: _____
ADDRESS: RD 2, Box 428 PLAT NO.: Po 143-121-12 Lot #1 2nd Duplex
COUNTY: Charlotte, N.C. 28210 LOT SIZE: Approx 40,000
LOCATION OF SITE: off Berlon Rd

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS 2-15% U	(S) 2-15% PS U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S 2-1 PS clay (U)	S (PS) Clay U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S massive PS ——— (U)	S (PS) Blocky U	S PS U	S PS U
4. SOIL DEPTH (In.)	S 48" PS (U)	(S) 40" PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Imprevious Strata, Rock)	(S) None PS U	(S) None PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) 72" To PS ground U water	(S) 72" to PS ground U water	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S slow PS v. slow (U)	S moderate (PS) U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S 1 mod-good PS Area (U)	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable	unsuitable		
SOIL SERIES	W. Ilas Mecklenburg	Cat. I		

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)


Recommendations/Comments: _____

Described By: William H. Marks

Title: Soil Scientist Date: 7-30-79

DHS Form 2601 (2/77)
Sanitation

2


200'
200'
200'
200'
Mobile Home
Mobile - in house

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 15962
T.C.NO. po 143-121-12
MAP DATE 1/3/79
DATE 7/31/79

NAME OF OWNER The Lamb's Chapel--Harry Bizzell 4411 Lake Rd

ADDRESS OF OWNER Route 2, Box 423 Charlotte, NC 28210

LOCATION OF LOT off Borden Road (Lake Road)

At your request and pursuant to Section .1900 of the North Carolina Administrative Code, Title 10, Department of Human Resources, Chapter 10, Health Services, Subchapter 10A, a site evaluation has been made for an on premises ground absorption sewage disposal system on the property designated above and the following conditions were found:

Soil Structure Massive
Soil Permeability Unsuitable

Sites classified as Unsuitable are not acceptable for soil absorption of sewage effluent. However, if engineering, geologic, soil, and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be expected to function satisfactorily, such sites may be re-classified as Provisionally Suitable. (Section 10 of the North Carolina Administrative Code 10 A,.1910)

If you desire to file for permission to install an "alternate or modified" system, you should present this office with your proposals in the form of plans and specifications. These would be reviewed and if it is found that the system may reasonably be expected to function satisfactorily, approval may be given on the execution by you of a "Septic Tank Agreement Form" available in this office.

John R Adkisson

John R. Adkisson, Environmentalist

R

SEE INSTRUCTIONS ON BACK

Date Received 12-17-80

ICAR (S) Application No [redacted] 15962

P.O.T C. No. 143-12-12


Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Department of Environmental Health for a permit to:

1) ✓ Install or Construct 2) _____ Alter or Repair an individual septic tank wastewater treatment system with a subsurface, soil absorption, effluent discharge.



3) PLOT PLAN (ACCURATELY DIMENSIONED)

4) Mobile Home ___ Yes ✓ No
Residence ✓ Yes ___ No

4) No of Bedrooms 3

5) Business Use -- Max No Employees _____

6) Washing Machine ✓ Yes ___ No

7) Garbage Disposal ___ Yes ✓ No

8) Dishwasher ___ Yes ✓ No

9) Water Supply
A) Individual Well _____
B) Governmental System _____
C) Community System
1) Well source ✓
2) Governmental source _____

10) Sewage System
House located within 200 feet of public sewer ___ Yes ✓ No
House located within 200 feet of community sewer ___ Yes ✓ No

11) FHA Case No _____

12) VA Case No _____

13) NAME OF OWNER The Lamb's Chapel (Harry Bizzell)
LAST FIRST MIDDLE

14) ADDRESS OF OWNER Rt 2 Box 428 (Boulevard Rd)

15) PHONE NO Home 523-6581 Office _____

16) LOCATION OF SYSTEM (4411 Lolie Rd)
STREET OR COUNTY ROAD

17) SUBDIVISION _____ Lot No. _____ Block No. _____

Map Book No 143 Page No. 12

18) DEED REFERENCE — DEED BOOK 3495 AT PAGE 563

19) HAS A SOIL INVESTIGATION BEEN RUN? _ YES _ NO DATE RUN _____

20) PTR NUMBER (See Instructions) _____


The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

17 December 1980
DATE OF APPLICATION


Harry Bizzell
OWNER

EHG-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY



5 drain pipe 99' long 3' on center
1485 sq foot bottom area.



15" minimum cover
1" stone over pipe
4" drain pipe
12" under pipe
6" sand

Proposed septic Tank system submitted for consideration and approval

Apt No. 15962

The Lynch Chapel
Mary Bizzell

Bed System

15962

LA No. [redacted]

Serial No. 4640

Date Issued Dec. 17, 1980

T. C. No. po 143-121-12

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

TO THE BUILDING INSPECTION DEPARTMENT

CERTIFICATE OF COMPLETION

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER The Lamb's Chapel (Harry Bizzell)
LAST FIRST MIDDLE

ADDRESS OF OWNER Route 2, Box 428, Charlotte, NC ZIP 28210

LOCATION OF LOT 4411 Lake Road
STREET OR COUNTY ROAD

SUBDIVISION _____ LOT NO. _____ BLOCK NO. _____

MAP BOOK NO. _____ PAGE NO. _____

The above specified lot is approved by the Mecklenburg County Department of Environmental Health for the installation of an individual septic tank system with subsurface, soil absorption effluent discharge based on the soil investigation, on an on-site inspection of the said lot; and upon the information supplied in the "Application for an Installation, Construction, Alteration, and/or Repair Permit", number – 17263 This approval is subject to the following terms and conditions:

1. That the nitrification field be installed, constructed, altered and/or repaired in the same area where the soil investigation was run

2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altred, and/or repaired and that the system be installed in accordance with same

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic tank system is not being installed, constructed, altered and/or repaired in accordance with a valid Installation, Construction, Alteration, and/or Repair Permit

John R Atkeson

Environmentalist

Environmental Health Director, or Authorized Section Head

EHD-5-76

Environmental Health Department's Copy