Date Received 2/20/76 Apt. No. (S) _____ Application No. (W) 10363

T. C. No. 001-052-15

Map Date _____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR WELL WATER SUPPLY PERMIT

NAME OF OWNER Hagler (LAST) William (FIRST) Caldwell

ADDRESS OF OWNER 6323 Robinson Church Rd (STREET OR COUNTY ROAD) Charlotte (CITY) NC. (STATE) Middle (ZIP) 28215

PHONE NO. Home 537-932 Office 376-2271

LOCATION OF PROPERTY Vance Road (STREET OR COUNTY ROAD)


SUBDIVISION Joint Property LOT NO. 15 BLOCK NO. _____

MAP BOOK NO. 15 PAGE NO. 171 FHA LOAN No

DEED REFERENCE: DEED BOOK 2058 PAGE NO. 391 VA LOAN No

WELL CONTRACTOR Moore Baker LICENSE NO. _____

Application is hereby made to the Mecklenburg County Health Department for a permit to drill a water well on the hereinabove described lot to be used as a source of _____ individual, _____ semi public, or _____ public water supply:



ACCURATELY DIAGRAM & DIMENSION LOT

2-20-76
DATE OF APPLICATION

William Caldwell Hagler
OWNER

Application approved and permit hereby granted

Permit No: 10363

Samuel Spencer Jr
ENVIRONMENTALIST

2/27/76

FORM NO. E-20-5-1-73

HEALTH DEPARTMENT'S COPY

Date Received 12/17/75

APT No. 10363

T. C. No. 001-052-15

Map Date 9/1/79

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Hagler (LAST) William (FIRST) Caldwell (MIDDLE)

2) ADDRESS OF OWNER 6323 Robinson Church Road W Charlotte, NC ZIP 28215

3) PHONE NO. Home 537-6932 Office 374-2271


4) LOCATION OF PROPERTY Nantz Road (STREET OR COUNTY ROAD)

5) SUBDIVISION Point Largo LOT NO 15 BLOCK NO

MAP BOOK NO 10 PAGE NO 171

6) DEED REFERENCE DEED BOOK 2458 PAGE NO 381

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot here nabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

William C Hagler
OWNER

FORM NO. EI-11-3M-6-75

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation December 18, 1975 APT NO. 10303

Owner W.C. Caldwell

Location of Property NANTZ ROAD TCN 001-052-15

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Cecil			
2. Soil Slope	acceptable 2-6%			
3. Soil Depth	acceptable >48"			
4. Soil Texture	acceptable clayey			
5. Soil Structure	acceptable subangular blocky			
6. Restrictive Horizons	—			
7. Soil Drainage	acceptable watertable >6'			
8. Soil Permeability (Percolation Rate)	acceptable 60 min/in			
9. Other	—			
10. Overall Rating	acceptable			


Recommendations Based on this investigation, the lot is recommended for approval for installation of a septic tank system. System design should be based on a percolation rate of 60 min/in.

See diagram on back

G Edward Caviness
Soil Scientist

CVK
3/18/75
HHD 539

DIAGRAM OF PROPERTY



3/18/75

END 539

Serial No. 5993

PTR No. 10363

001-252-15

T C No.

Date Issued 12/19/75

9-7-74

Map Date

Do Not Issue A Building Permit Based On This Form

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION


PERCOLATION TEST REPORT

NAME OF OWNER Hagler (LAST) William (FIRST) Caldwell (MIDDLE)

ADDRESS OF OWNER 6313 Robinson Church Road, West ZIP 28215

LOCATION OF PROPERTY Nantz Road (STREET OR COUNTY ROAD)

SUBDIVISION Point Largo LOT NO 15 BLOCK NO



PLOT PLAN

This is to certify that a percolation test has been run and an on-site inspection made by the Mecklenburg County Health Department on the lot described above. The said test was conducted on that portion of the lot as indicated on above plot

The percolation rate determined by the test was *60Min./In. The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge subject to the following terms and conditions

1. A permit to install, construct, alter, or repair the specific system shall be obtained from the Mecklenburg County Health Department prior to the beginning of any construction of buildings, or of the wastewater treatment system on the said lot.
2. The size of the septic tank wastewater teratment system which must be installed will be determined by the Health Department prior to installation based on the percolation rate obtained above, and on the size and type of building constructed thereon.
3. This approval is valid only if the system is installed in the immediate area where the percolation test was run.
4. This approval is void if any grading, filling, or construction (including the drilling of a well) is performed on the lot which, in the opinion of the Health Department, renders the area where the percolation test was run unsuitable for the installation, construction, alteration, and/or repair of such a system.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina State Board of Health and the Mecklenburg County Board of Health which were in effect on the date of issuance and is void if at any time in the future, prior to the completion of the system, these laws, rules, and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

*Results determined by soil analysis

W. Laurence Wright
Soil Scientist

Director, Environmental Health Division or Authorized Section Head

FORM NO. E-2-4-1-71

HEALTH DEPARTMENT'S COPY

Date Received 12/19/75

ICAR(S) Application No. 10363

T.C. No. 001-052-15

Map Date 9-9-74

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to

1) ✓ Install or Construct 2) ___ Alter or Repair an individual septic tank wastewater treatment system with a subsurface, soil absorption, effluent discharge

3) PLOT PLAN (ACCURATELY DIMENSIONED)

4 No. of Bedrooms 3

5 Busines. Use Max No Employees ___

6 Washing Machine ✓ Yes ___ No

7 Garbage Disposal ___ Yes ___ No

8 Dishwasher ✓ Yes ___ No

9 Water Supply
- A) Individual Well ✓
- B Governmental System ___
- C Community System
  - 1 Well source ___
  - 2 Governmental source ___

10 Sewage System
House located within 200 feet of public sewer ___ Yes ✓ No
House located within 200 feet of community sewer ___ Yes ✓ No

11 FHA Case No. NONE

12 VA Case No. NONE

13) NAME OF OWNER Nagler (LAST) William (FIRST) Caldwell (MIDDLE)

14) ADDRESS OF OWNER 6323 Providence Church Road West Charlotte NC 28215

15) PHONE NO. Home 537-1532 Office 374-2271

16) LOCATION OF SYSTEM Nance Road (STREET OR COUNTY ROAD)

17) SUBDIVISION Point Large Lot No. 15 Block No. ___

Map Book No ___ Page No. ___

18) DEED REFERENCE — DEED BOOK ___ AT PAGE ___

19) HAS A PERCOLATION TEST BEEN RUN? ✓ YES ___ NO DATE RUN 12/15/75

20) PTR NUMBER (See Instructions) 10363

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

DATE OF APPLICATION

William Caldwell Nagler
OWNER

FORM NO. E-4-4-1-71

HEALTH DEPARTMENT'S COPY

Date Issued 2/20/76

Serial No. 5662

IMPROVEMENTS PERMIT

LA No. 10363

T C No. 001-052-15

Map Date 9-9-74

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Hagler (LAST) William (FIRST) Caldwell (MIDDLE)

ADDRESS OF OWNER 6323 Robinson Church Road, West ZIP 28215

LOCATION OF LOT Nance Road (STREET OR COUNTY ROAD)

SUBDIVISION Point Largo LOT NO. 15 BLOCK NO

MAP BOOK NO PAGE NO

The above specified lot is approved by the Mecklenburg County Health Department for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge based on the percolation test results which yielded a percolation rate of 60Min./Inch an on-site inspection of the said lot; and upon the information supplied in the "Application for an Installation, Construction, Alteration, and/or Repair Permit", number 10363. This approval is subject to the following terms and conditions:

1. That the nitrification field be installed, constructed, altered, and/or repaired in the same area where the percolation test was run.
2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altred, and/or repaired and that the system be installed in accordance with same.

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic-tank system is not being installed, constructed, altered and/or repaired in accordance with a valid Installation, Construction, Alteration, and/or Repair Permit

Environmentalist

Director, Environmental Health Division or Authorized Section Head

FORM NO E-3-8-1-72

HEALTH DEPARTMENT'S COPY

Date Issued 14 June 1976 Serial No. 7592 ICAR Permit No 10363

T C No 001-052-15

Map Date 9-9-74


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

INSTALLATION, CONSTUCTION, ALTERATION, AND/OR REPAIR PERMIT

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Permission is hereby granted to ✓ Install or Construct Alter or Repair the individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge as specified herein at the described location. This permit is granted based upon the information supplied in application 10362, dated 12/19/75 and this permit shall be void and of no effect if the information provided in the application is not true. All work shall be completed on or before 10 July 1976 after which date this permit shall be null and void.



PLOT OF SYSTEM

Persons to be Served 60

Liquid Capacity of Septic Tank 1500

Tank Construction pre cast

Absorption Area in Square Feet or Number of Trenches and Length of Lines

Total Absorption 600 & 150

Number of Bedrooms

Distance from House 10'

Distance from Property Lines 10'

Distance from Well 50' +

NAME OF OWNER Hagler William Caldwell

LOCATION OF PROPERTY Nanty Road Lot 15

The system shall meet all of the construction requirements as set forth in the Regulations of the Mecklenburg County Board of Health which are in effect on the date of the granting of this permit. A certificate of approval must be issued by the Health Director before any system can be covered up or otherwise rendered uninspectable or can be used

Comments in bed 15'x100'x12"

John R Atkinson

Division or Section Head

Environmentalist

If this permit is for the installation or construction of a new system, it must be signed by the division or section head of the Environmental Health Division in order to be valid. Only the signature of the Environmentalist is required where an existing system is being altered or repaired

FORM NO E-S-4-2M-6-75

HEALTH DEPARTMENT COPY

Date Issued 22 June 1976 Serial No. 7052

C of A (s) No 10363

T C No 001-052-15

Map Date 9-9-74

John M Atkinson

CERTIFICATE OF COMPLETION

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

CERTIFICATE OF APPROVAL

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Name of Owner Hagler William C (FIRST) (MIDDLE)

Location of Property Nantz Rd Lot 15

Application Number 10363 Permit Number 10363

Inspection Date:

Liquid Capacity of Tank 1500 Tank Material precast

Total Length of Drain Tile 600 & 150 Number of Lines 6 & 4

Depth of Filter Material 12" Cover Depth 18"-24"

Water Supply Source well Distance from Water Source 50'

Excavation Inspected — (DATE) Tank Inspected 6-22-76 (DATE)

Nitrification Field Inspected 6-22-76 (DATE)

Washing Machine Line Inspected, If Applicable 6-22-76 (DATE)

The undersigned has inspected the Individual Septic Tank System with subsurface, soil absorption, effluent discharge as described above and it has been ✓ installed or constructed, _____ altered or repaired in accordance with the permit issued and the regulations of the Mecklenburg County Board of Health in effect on the date of issuance of the permit. The issuance of this Certificate of Approval does not in any way guarantee that the system will operate properly or relieve any person now or hereafter owning, controlling, or using such system from any liability resulting from the failure of the system to operate properly. This Certificate of Approval is issued subject to those restrictions and conditions shown on the permit(s) in addition to those listed below under comments. This Certificate of Approval shall be null and void if any information contained in the application is untrue or if any additions are made to the property which would increase the requirements for said system.

Comments: installed as permitted

John M Atkinson

Environmentalist

FORM NO E-S-EM-6-75

HEALTH DEPARTMENT COPY