Date Received 11-19-73

APT No. 7247

T. C. No. 215-167-12

Map Date 6-10-74

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER RALPH SQUIRES CONSTRUCTION CO. INC.
(LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER 2600 MILTON ROAD ZIP 28205

3) PHONE NO. Home _____ Office 537-9553


4) LOCATION OF PROPERTY 13500 ANDULUSIAN DRIVE
(STREET OR COUNTY ROAD)

5) SUBDIVISION WINDROW ESTATES LOT NO. 5 BLOCK NO. F

MAP BOOK NO 16 PAGE NO. 173

6) DEED REFERENCE: DEED BOOK 3438 PAGE NO. 445

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Jim Bogan
OWNER

FORM NO. E-1-8-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. 4-4-74
2. _____
3. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

SDR No. 7247
T.C. No. ~~portion of~~ 215-~~18E-02~~
~~5-3-72~~
6-10-74

NAME OF OWNER Ralph Squires Construction Co., Inc.

ADDRESS OF OWNER 2600 Milton Road ZIP 28205

LOCATION OF LOT 13500 Andulusian Drive, Lot 5-F

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
____	1.	_____	_____ min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

X ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) 4-1-74 - Soils over the majority of the lot are of the Chewacla series. These soils have a seasonal high water table within 18 inches of the soil surface and are subject to flooding. These soil characteristics result in inadequately slow permeability and percolation rate.

W. Lynch
Soil Scientist

_____
Environmentalist

(Stencil No.)
EHD 398
8/70

FORM NO.
E-19-8-14-70

MECKLENBURG COUNTY HEALTH DEPARTMENT

INTER-OFFICE COMMUNICATION

DATE: April 3, 1974

TO: Moffitt Kirby
Environmentalist

FROM: W. Everette Lynn, Jr. wel
Soil Scientist

SUBJECT: APT #7247 (Ralph Squires Construction Co.)
Lot No. 5-F 13500 Andulusian Drive
Windrow Estates Subdivision

4-1-74

Soils over the majority of the lot are of the Chewacla series. These soils have a seasonal high water table within 18 inches of the soil surface and are subject to flooding. These soil characteristics result in inadequately slow permeability and percolation rate.

Based on this investigation, the lot appears unsuitable for installation of a septic tank system.

WEL:jdg